
Temperature and Humdity Monitor





Digital Thermo Hygrometer



Functions

- Measure temperature
- Measure relative humidity

Applications

- Measure ambient temperature
- Measure non-condensing relative humidity

Features

- Displays temperature and relative humidity at the same time
- Large digit LCD display
- Comfort indicator
- Maximum/Minimum
- 1-Year limited warranty

Includes

- Batteries
- Manual

Specifications

Temperature Range	-58° To 158°F (-50° To 70°C)
Relative Humidity Range	20% To 99.9% (Non-Condensing)
Accuracy Temperature	±1.8°F (1.0°C) Range of -4° To 158°F (-20° To 70°C) or ±4.0°F (2.0°C)
Resolution Temperature	0.1°
Resolution Rh	0.1%
Operating Temperature	32° To 122°F (0° To 50°C)
Battery Type	AAA
Warranty	1 Year

Downloads



Manual



Data Sheet

H25-116



Made in CHINA